

# INFORMATION ONLY

## E8267D-09A

# S E R V I C E N O T E

Supersedes:  
E8267D-09

## E8267D Vector Signal Generator

Serial Numbers: ALL

Unexpected loss or change to WRM files in volatile memory in instruments with option 601 or 602.

### Parts Required:

P/N	Description	Qty.
None		

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
<b>INFORMATION ONLY</b>	
<input type="checkbox"/> Calibration Required <input checked="" type="checkbox"/> Calibration NOT Required	PRODUCT LINE: 15 AUTHOR: PY
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2014  
PRINTED IN U.S.A.

April 18, 2014

Rev. 22



**Situation:**

Unexpected loss or change to WFM files in volatile memory in instruments with option 601 or 602 for firmware C.04.32 and below.

**Solution/Action:**

Upgrade firmware to the latest, at the time of posting it's C.6.21.

**Revision History:**

Revision Number	Date	Author	Reason For Change
1.0	14-Apr-14	Petrina Yong	As published