## E8363B-06A

# SERVICE NOTE

Supersedes: E8363B-06

## E8363B PNA Series RF Network Analyzers

Serial Numbers: US00000000/US999999999 and MY00000000/MY999999999

Replace Inverter board (0950-3379) due to faulty component.

To Be Performed By: Agilent-qualified personnel or customer with

specific product repair knowledge - requires

instrument disassembly and component replacement.

**Parts Required:** 

P/N Description Qty. 0950-3379 DC/AC Inverter Board 1

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:				
MODIFICATION RECOMMENDED				
ACTION CATEGORY:	IMMEDIATELY ON SPECIFIED FAILURE X AGREEABLE TIME	STANDARDS LABOR: 0.2 Hours		
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE X ON-SITE X SERVICE CENTER	SERVICE INVENTORY:	RETURN X SCRAP SEE TEXT	USED RETURN PARTS: X SCRAP SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: ALWAYS		
AUTHOR: MF		PRODUCT LINE: WN		
ADDITIONAL INFORMATION: Affected PNA models: E8356/7/8A, E8801/2/3A, N3381/2/3A, N5230A, E8361/2/3/4A, E8362/3/4B. Service Note History: -06a, April 08, Change from Mod. Available to Mod. Recommended.				

© AGILENT TECHNOLOGIES, INC. 2008 PRINTED IN U.S.A.



Page 1 of 2

April 29, 2008

Rev. 14

Page 2 of 2 E8363B-06A

#### **Situation:**

The original fuse (see photo) in the DC/AC Inverter board (p/n 0950-3379) is prone to failure in normal use.

#### **Solution/Action:**

Replace the Inverter board with a board containing the new fuse (see photo).

