F9642A-02



Implemented During Normal Course of Providing Support

> Supersedes: [NONE]

F9642A- 2D MPAC Pro for FR1 4x4 functional throughput and FR2 2x2 Testing

Serial Numbers: TW63110001, TW63110002, TW63110003, TW63110006, TW63110007, TW63110008, TW63110010, TW63110011, TW63110012, TW63110013, TW63110015, TW63110016, TW63110017, TW63110018, TW63110019, TW63110020, TW63110021, TW63110025, TW63110022, TW63110023, TW63110024, TW63110029

POSSIBLE <u>"CUT INJURY</u>" HAZARD

WARNING HAZARD CLASS 2

The Problem – Door handle used on chamber's door potentially has sharp edge that can cause a hand laceration on operator

Parts Required:

1520-0734

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[[]] ON SPECIFIED FAILURE [X] AGREEABLE TIME	STANDARDS LABOR: 2 Hours	
LOCATION CATEGORY:	[]] SERVICE CENTER [X] ON-SITE (active On-site contract required) []] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: X SCRAP [[]] SEE TEXT [[]] SEE TEXT	
AVAILABILITY	/: EOS	NO CHARGE AVAILABLE UNTIL: ALWAYS	
	[[]] Calibration Required [X] Calibration NOT Required	PRODUCT LINE: [PL13] AUTHOR: [P.U]	

ADDITIONAL INFORMATION:



Situation:

It was reported that one door handle used for the door of our 2DMPAC pro chamber has a sharp edge that has caused a hand laceration on the end user during normal operation of the door

Solution/Action:

Support Engineering has followed PSE process. The resolution of the process is to add a rubber cushion sleeve as an available upgrade to customer entitled. It will be created as a KPN and will be deployed to selected serials of F9642A 2D Multi-Probe Anechoic Chamber (MPAC) Pro chambers to cover the handles and eliminate the future potential risk.

Revision History:

Date	Service Note Revision	Author	Reason for Change
06 Sep 2024	01	Patricio Ugarte Garcia	As Published
00 000 2024	01		