
J2219A-02




ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	 IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME 	STANDARDS: Labor 1.0 Hour
LOCATION CATEGORY:	 CUSTOMER INSTALLABLE ON-SITE SERVICE CENTER 	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: 16 November 1995
AUTHOR: NB	ENTITY: 3800	ADDITIONAL INFORMATION:

© 1993 AGILENT TECHNOLOGIES
PRINTED IN U.S.A.



- 3. Carefully snap out LED display board assembly
- 4. Locate jumper and remove at one of either location as shown in the diagram



- 5. Reinstall wires/fasteners and board assembly
- 6. Test brightness operation