# S E R V I C E N O T E

SUPERSEDES: None

## **J2301A Internet Advisor**

**Serial Numbers:** 0000A00000 / 3432A00841

New replacement assemblies allow full speed operation when used with high speed parallel adapters

### **Assemblies:**

5063-6239	DOS 16MegBytes Board Assembly
5063-6241	Exchange DOS 5063-6239
5063-6238	DOS 4MegBytes Board Assembly
5063-6240	Exchange DOS 5063-6238

Continued

DATE: October 1994

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: Labor 1.5 Hours			
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE RETURN USED RETURN INVENTORY: SCRAP SEE TEXT SEE TEXT			
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: October 1996			
AUTHOR: NB	ENTITY: 0800	ADDITIONAL INFORMATION:			

© 1994 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



## **Situation:**

The Parallel Port design does not allow full speed operations when used with High Speed Parallel adapters.

	New Assembly	Old Assemblies
16MByte (New)	5063-6239	5063-5160, 5063-1873
16MByte(Exch)	5063-6241	5063-5134
4MByte (New)	5063-6238	J2300-62902, 5063-1872
4MByte (Exch)	5063-6240	5063-5133

## **Solution/Action:**

The old DOS assembly resident within the instrument must be exchanged with one of the new assemblies listed above.