J2302B-06

S	Е	R	V	I	С	Е	Ν	0	Т	Ε
							SUPERSED	ES: None	)	
J23	802B A	dvisor	undero	eradle	•					
Seri	ial Numb	ers:	US353 US353 US353	50744	US3535 US3535 US3535	50803		US3535( US3535( US3535(	0986	
Un	dercrad	le inte	rface ca	ard Lo	ong Lead	ds sh	ort to chassi	s		
	<b>ts Requi</b> r 95-66502		adle Adap	oter						
The show		hassis if	the J2295	-			used to connect a ds are not cut. T		•	
	<b>ition:</b> lace bad a	assembly	with J22	95-665	02.					
							DATE: June	1996		

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:							
	<b>MODIFICATION</b>	RECOMMENDED					
ACTION CATEGORY:	<ul> <li>IMMEDIATELY</li> <li>ON SPECIFIED FAILURE</li> <li>AGREEABLE TIME</li> </ul>	STANDARDS: Labor 0.5 Hour					
LOCATION CATEGORY:	<ul> <li>CUSTOMER INSTALLABLE</li> <li>ON-SITE</li> <li>SERVICE CENTER</li> </ul>	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT					
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: June 1998					
AUTHOR: NB	ENTITY: 3801	ADDITIONAL INFORMATION:					

© 1996 AGILENT TECHNOLOGIES
PRINTED IN U.S.A.

