

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

SN J3953B-02

S E R V I C E N O T E

Supersedes:
NONE

J3953B VQT

Serial Numbers: [0000A00000 / 9999Z99999]

Repair of the J1981B will now require Service centers to replace all disturbed electrical tape during repairs.

Parts Required:

P/N	Description	Qty.
0460-2968	Tape, Electrical	As needed

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: DM PRODUCT LINE: 2J

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2004
PRINTED IN U.S.A.



Agilent Technologies

April 26, 2004

Situation:

During the disassembly of the J3953B it is often necessary to disturb the electrical tape used inside the unit for cable management.

Solution/Action:

Service centers will need to order the tape specified and have it available when repairing the J3953B. Do not reuse tape that is present, replace it as part of the re-assembly.