

M1740A-01

Information Only Service Note

Supersedes:
[NONE]

M1740A – mmWave Transceiver

Serial Numbers: MY58270000-MY58279999 and US58230000-US58239999

The Problem – M1740A Revision 5 RRH (MY5827xxxx and US5823xxxx) are no longer manufactured. These have been replaced by the M1740A Revision 6 RRH

Parts Required:

M1740-60862 – Subassy, mmWave Transceiver, Rev 6
Replacement M1740A RRH for Revision 5 RRH when no repair material is available.

ADMINISTRATIVE INFORMATION

<input type="checkbox"/> Calibration Required	PRODUCT LINE: 13
X Calibration NOT Required Calibration NOT Required	AUTHOR: MJW

ADDITIONAL INFORMATION:

Situation:

The M1740A RRH (Rev 5) mmWave transceiver modules. Serial numbers MY5827xxxx and US5823xxxx are no longer manufactured

The repair procedure for M1740A RRH Rev5 mmWave transceiver modules is to use and exchange RF core. Part number M1740-60860 or M1740-69860 If there is no Rev 5 replacement part available. You must use M1740-60862 as the replacement.

M1740-60862 – Subassy, mmWave Transceiver, Rev 6
Replacement M1740A RRH for Revision 5 RRH when no repair material is available.
The replacement M1740A will have a new serial number and requires product replacement to be performed in Siebel service records.

Solution/Action:

M1740-60862 – Subassy, mmWave Transceiver, Rev 6
Replacement M1740A RRH for Revision 5 RRH when no repair material is available.
The replacement M1740A will have a new serial number and requires product replacement to be performed in Siebel service records.

Revision History:

Date	Service Note Revision	Author	Reason for Change
28 August 2019	01	Michael Woichik	As Published