

Information Only Service Note

Supersedes:
NONE

N1125A – x1149 Boundary Scan Analyzer

Serial Numbers: All

Manufacturing ID Number: All

The Problem – Keysight CCL License patch update version 5.5.1 release

Parts Required:

P/N	Description	Qty.
NONE	NONE	NONE

ADMINISTRATIVE INFORMATION

Calibration Required

PRODUCT LINE: PL80

Calibration NOT Required

AUTHOR: M N Yovendiran

ADDITIONAL INFORMATION:


NONE

Situation:

The x1149 “Keysight.Ccl.Licensing.Api.dll” of CCL version 5.5.1 software update patch release

Solution/Action:

1. Uninstall the previous software revision of Keysight x1149 Boundary Scan Analyzer.
2. Download Keysight x1149 Boundary Scan Analyzer Software Revision 1.7.2 from [Keysight x1149 Keysight CCL License patch update version 5.5.1 release | Keysight](#)
3. Install the Keysight x1149 Boundary Scan Analyzer Software Revision 1.7.2.
 - a. Please run the software in elevated mode.



4. Congratulations! “Keysight License Manager” and Keysight License Service” is successfully updated to **Version 5.5.1** and you are now using Keysight x1149 Boundary Scan Analyzer Software Revision 1.7.2. Proceed with normal activities.

Revision History:

Date	Service Note Revision	Author	Reason for Change
11 May 2023	01	M N Yovendiran	As Published