N1914A-09

Modification Recommended Service Note

Supersedes: NONE

N1914A EPM Series Dual-Channel Power Meter

Serial Numbers:	MY57140003	MY57160020	MY57160025	MY57170002	MY57170003
MY57170004	MY57170005	MY57180002	MY57190002	MY57190003	MY57190004
MY57190005	MY57190007	MY57190008	MY57190009	MY57190010	MY57190011
MY57190012	MY57190013	MY57190014	MY57190015	MY57190016	MY57190017
MY57190018	MY57190019	MY57190020	MY57190021	MY57210002	MY57210003
MY57210004	MY57210005	MY57210006	MY57210007	MY57210008	MY57210009
MY57210010	MY57210011	MY57210012	MY57210013	MY57210015	MY57210017
MY57210018	MY57210019	MY57210021	MY57210022	MY57210023	MY57210029
MY57230002	MY57230003	MY57230004	MY57230005	MY57230006	MY57230007
MY57230008	MY57230009	MY57230010	MY57230011	MY57230012	MY57230013
MY57230014	MY57230015	MY57240032	MY57240034	MY57260002	MY57260003
MY57260004	MY57260005	MY57260006	MY57260007	MY57260008	MY57260009
MY57260010	MY57260011	SG57230006	SG57230007	SG57230008	SG57230009

Loosen power reference connector assembly ADMINISTRATIVE INFORMATION

2255	ON SPECIFIED FAILURE AGREEABLE TIME	STANDARDS LA	BOR: 2 Hours		
LOCATION [[]] CATEGORY: [[]] X	CUSTOMER INSTALLABLE ON-SITE (active On-site contract required) SERVICE CENTER CHANNEL PARTNERS	SERVICE: INVENTORY:	[]] RETURN	USED PARTS:	[[]] RETURN [[]] SCRAP X SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 01-Oct-2018			
X [[]]	Calibration Required Calibration NOT Required	PRODUCT L AUTHOR:			

ADDITIONAL INFORMATION:



Parts Required:

P/N Description Qty.

NONE

Situation:

Keysight recently discovered a loose power reference connector assembly in the power meter which may result in a lower accuracy of the 1mW Power Reference. This may cause an additional power measurement error of up to 1.0%.

We would recommend customers to return the Power Meter model number and serial number listed above to the nearest Keysight Service Center for repair.

Solution/Action:

Please contact Keysight Technologies' Customer Contact Center at www.keysight.com/find/contactus for the recommended product modification.

Revision History:

Date	Service Note Revision	Author	Reason for Change	
10-0ct-2017	01	CKN	As Published	