N5102A-01 <u>S E R V I C E N O T E</u>

Supersedes: None

N5102A Baseband Studio Digital Signal Interface Module

Serial Numbers:

US43310096	US43310101	US43310439	US43310641
US43310097	US43310123	US43310395	US43241618
US43310303	US43310107	US43310330	US43241625
US43310295	US43310143	US43310318	
US43310297	US43310155	US43310529	
US43310569	US43310163	US43310531	
US43310504	US43310159	US43310542	
US43310533	US43310193	US43310556	
US43310091	US43310168	US43310570	
US43310112	US43310178	US43310629	

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	[[]] ON SPECIFIED FAILURE X AGREEABLE TIME	STANDARDS LABOR: 0.0 Hours			
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE [[]] ON-SITE [[]] SERVICE CENTER [[]] CHANNEL PARTNER	SERVICE [[]] RETURN INVENTORY: [[]] SCRAP X SEE TEXT	USED PARTS:	[[]] RETURN X SCRAP [[]] SEE TEXT	
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 4/1/2011			
AUTHOR: HLU		PRODUCT LINE: 15			
ADDITIONAL INFORMATION: This Service Note applies to Japan ONLY and provides for a free replacement of power supply module that does not have the "PSF" mark					

© AGILENT TECHNOLOGIES, INC. 2009 PRINTED IN U.S.A.



April 8, 2009

Rev. 16

Page 2 of 2 N5102A-01

N5102As were shipped to Japan without the proper "PSE" mark on the power supply module. This service note provides free replacement of the module with one with the proper "PSE" marking for Japan customers only.

Parts Required:

P/N	Description	Qty.
0950-4540	Power module	1

Situation:

N5102As were shipped to Japan without the proper "PSE" mark on the power supply module. This service note provides free replacement of the module with one with the proper "PSE" marking for Japan customers only.

Solution/Action:

Replace customer power supply modules with a module with the correct marks. Notification of customers will be accomplished by the Japan Field Quality team.