Modification Recommended Service Note

Supersedes: NONE

N5750A DC System Power Supply

Serial Numbers: Refer to Table 1

The Problem – Current programming and readback accuracy may marginally out of specification.

Parts Required:

NONE

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 1 Hour		
LOCATION	[X] SERVICE CENTER	SERVICE: [[]] RETURN USED [[]] RETURN		
CATEGORY:	[[]] ON-SITE (active On-site contract required) [[]] CHANNEL PARTNERS	INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP [X] SEE TEXT [X] SEE TEXT		
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 8 th March 2025		
	[X] Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: SP AUTHOR: LIM ZHAN MING		

ADDITIONAL INFORMATION: No impact on service inventory Not applicable



Situation:

For units listed in Table 1, the current programming and readback accuracy may marginally out of specification.

Solution/Action:

Kindly contact Keysight Technologies Customer Contact Center at www.keysight.com/find/contactus for sending the affected unit back to service center.

Service center to perform performance verification on current programming and readback accuracy.

If performance verification PASSES

No action needed

If performance verification FAILS

• Calibrate (adjustment) the unit

Table 1: Affected Serial Number

US23D6226R	US23D6229R	US23J6811R	US23J6862R
US23D6227R	US23D6230R	US23J6818R	US23J8201R
US23D6228R	US23D6231R	US23J6842R	US23M3164R

Revision History:

Date	Service Note Revision	Author	Reason for Change
29th Feb 2024	01	LIM ZHAN MING	As Published