# Modification Recommended Service Note

Supersedes: NONE

# N5767A DC System Power Supply

Serial Numbers: Refer to Table 1

The Problem – Current programming and readback accuracy may marginally out of specification.

# Parts Required:

NONE

#### ADMINISTRATIVE INFORMATION

ACTION	[X] ON SPECIFIED FAILURE	STANDARDS
CATEGORY:	[]] AGREEABLE TIME	LABOR: 1 Hour
LOCATION CATEGORY:	[X] SERVICE CENTER [[]] ON-SITE (active On-site contract required) [[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: [X] SEE TEXT [X]
AVAILABILITY	: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 8 <sup>th</sup> March 2025
	[X] Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: SP AUTHOR: LIM ZHAN MING

ADDITIONAL INFORMATION: No impact on service inventory Not applicable



# Situation:

For units listed in Table 1, the current programming and readback accuracy may marginally out of specification.

# Solution/Action:

Kindly contact Keysight Technologies Customer Contact Center at <a href="https://www.keysight.com/find/contactus">www.keysight.com/find/contactus</a> for sending the affected unit back to service center.

Service center to perform performance verification on current programming and readback accuracy.

If performance verification PASSES

No action needed

If performance verification FAILS

• Calibrate (adjustment) the unit

Table 1: Affected Serial Number

US22L4021R	US22L4330R	US22L4342R	US23D6934R
US22L4042R	US22L4336R	US22L4351R	US23D6935R
US22L4113R	US22L4337R	US22L4360R	US23D6939R
US22L4327R	US22L4341R	US22L4361R	

Revision History:

Date	Service Note Revision	Author	Reason for Change	
29 <sup>th</sup> Feb 2024	01	LIM ZHAN MING	As Published	