# Modification Recommended Service Note

Qty.

1 1

Supersedes: None

## N6700C Low-Profile Modular Power System Mainframe, 400W, 4 Slots

Serial Numbers: MY56022094 - MY56305851, SG56000323, SG56000324, SG56000325, SG56100002

The Problem – Unit may not be able to power on when user switches on from the front panel.

Parts	Required:
P/N	

Description 5067-5091 Back Plane PCA LF 5185-1352 Insulator Back Plane

ADMINIST	RATIVE INFORMATION		
ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 1 Hour	
LOCATION CATEGORY:	[X] SERVICE CENTER [[]] ON-SITE (active On-site contract required) [[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [X] RETURN INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP [X] SEE TEXT [[]] SEE TEXT	
AVAILABILITY	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 01 Nov 2024	
	[[]] Calibration Required [X] Calibration NOT Required	PRODUCT LINE: SP AUTHOR: LIM ZHAN MING	

ADDITIONAL INFORMATION: No impact on service inventory



### Situation:

For the Serial Number listed in Table 1, unit may suddenly power off when operating and no longer can be powered on again when user switches on from the front panel.

### Solution/Action:

Kindly contact Keysight Technologies Customer Contact Center at <u>www.keysight.com/find/contactus</u> for sending the affected unit back to service center for inspection and repair.

\*Service center to perform inspection and confirm if the failure is on the backplane assembly. \*This service note is only meant for backplane failure (5067-5091).

#### Revision History:

Date	Service Note Revision	Author	Reason for Change
5 <sup>th</sup> Oct 2023	01	LIM ZHAN MING	As Published