

N6702C-05

# Modification Recommended Service Note

Supersedes: NONE

## N6702C Low-Profile Modular Power System Mainframe, 1200W, 4 Slots

Serial Numbers: Refer to Table 1

The Problem - Unit may not be able to power up when user switches on from the front panel

<b>Parts Required:</b> P/N	Description	Qty.
0950-5366	Power Supply Switching 48V 2600W Switching Single Output	1

#### ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 1.0 Hour
LOCATION CATEGORY:	<ul> <li>[]] CUSTOMER INSTALLABLE</li> <li>[]] ON-SITE (active On-site contract required)</li> <li>[X] SERVICE CENTER</li> <li>[]] CHANNEL PARTNERS</li> </ul>	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: [X] SCRAP [X] SEE TEXT [[]] SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 30th June 2023
	<ul><li>[]] Calibration Required</li><li>[X] Calibration NOT Required</li></ul>	PRODUCT LINE: [SP] AUTHOR: [LIM ZHAN MING]

The Service Inventory is not impacted



### Situation:

A specific batch (refer to Serial Number listed in Table 1) of lower-level material may cause the power on issue on N6702C. This will not cause any safety concern.

#### Solution/Action:

The affected unit with the serial number listed in Table 1 needs to be sent back to Keysight Service Center for the part (0950-5366) replacement .

Kindly contact Keysight Technologies Customer Contact Center at <u>www.keysight.com/find/contactus</u>

MY56100319MY56100330MY56100340MY56100352MY56100366MY561MY56100320MY56100331MY56100341MY56100355MY56100367MY561MY56100321MY56100332MY56100342MY56100356MY56100368MY561MY56100323MY56100333MY56100343MY56100357MY56100370MY561MY56100324MY56100334MY56100345MY56100358MY56100372MY561	00390 00391
MY56100321         MY56100332         MY56100342         MY56100356         MY56100368         MY561           MY56100323         MY56100333         MY56100343         MY56100357         MY56100370         MY561	00391
MY56100323 MY56100333 MY56100343 MY56100357 MY56100370 MY561	
	00392
MY56100324 MY56100334 MY56100345 MY56100358 MY56100372 MY561	00002
	00393
MY56100325 MY56100335 MY56100346 MY56100361 MY56100375 MY561	00400
MY56100326 MY56100336 MY56100347 MY56100362 MY56100377 MY561	00472
MY56100327 MY56100337 MY56100348 MY56100363 MY56100378 MY561	00474
MY56100328 MY56100338 MY56100349 MY56100364 MY56100386 MY561	00475
MY56100329 MY56100339 MY56100351 MY56100365 MY56100387	

Table 1: Affected Ser	rial Number
-----------------------	-------------

#### Revision History:

Date	Service Note Revision	Author	Reason for Change
1 <sup>st</sup> Jul 2022	01	LIM ZHAN MING	As Published