

# N6751A-01

## S E R V I C E N O T E

Supersedes:  
NONE

### N6751A 50 W High Performance DC Power Module

Serial Numbers: MY43001996/MY99999999

If a N6751A that has the LGA option and it is put in a mainframe with firmware that is earlier than C.02.06 or less, a "Channel Failed" error will occur.

**Parts Required:**

P/N	Description	Qty.
NONE		

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: MC    PRODUCT LINE: SP

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007  
PRINTED IN U.S.A.



July 6, 2007

**Situation:**

If a N6751A has the LGA option and it is used in a mainframe with firmware older than C.02.06 and the module is turning on with a “Channel Failed” error, the firmware needs to be updated. You can check the firmware revision by pressing Menu -> System -> About ->Frame.

**Solution/Action:**

Upgrade to the latest firmware. The newest firmware can always be found at <http://www.agilent.com/find/N6700firmware>. If this does not cause the error to go way, then the module will need to be replaced.