Modification Recommended Service Note

Supersedes: NONE

N8762A DC System Power Supply

Serial Numbers: Refer to Table 1

The Problem – Current programming and readback accuracy may marginally out of specification.

Parts Required: NONE

ADMINISTRATIVE INFORMATION

ACTION	[X] ON SPECIFIED FAILURE	STANDARDS		
CATEGORY:	[]] AGREEABLE TIME	LABOR: 1 Hour		
LOCATION CATEGORY:	[X] SERVICE CENTER [[]] ON-SITE (active On-site contract required) [[]] CHANNEL PARTNERS	SERVICE: []] RETURN USED []] RETURN INVENTORY: []] SCRAP PARTS: []] SCRAP [X] SEE TEXT [X] SEE TEXT		
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 8 th March 2025		
	[X] Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: SP AUTHOR: LIM ZHAN MING		
	INFORMATION: a service inventory le			

KEYSIGHT

Situation:

For units listed in Table 1, the current programming and readback accuracy may marginally out of specification.

Solution/Action:

Kindly contact Keysight Technologies Customer Contact Center at <u>www.keysight.com/find/contactus</u> for sending the affected unit back to service center.

Service center to perform performance verification on current programming and readback accuracy.

If performance verification PASSES

No action needed

If performance verification FAILS

• Calibrate (adjustment) the unit

US23D7043S	US23E1060S	US23H4195S	US23K0812S
US23E0403S	US23E1061S	US23H5249S	US23L1717S
US23E0404S	US23E1062S	US23K0810S	
US23E1059S	US23F2040S	US23K0811S	

Table 1: Affected Serial Number

Revision History:

Date	Service Note Revision	Author	Reason for Change
29 th Feb 2024	01	LIM ZHAN MING	As Published