

U2022XA-01

Information Only Service Note

Supersedes:
NONE

U2022XA 50 MHz to 40 GHz USB Peak and Average Power Sensor

Serial Numbers: MY55150007 MY55190002 MY55360010 MY55369008 MY55439009
MY55490013 MY56020022 MY56090003 MY56090007 MY56090009 MY56200006
MY56240003 MY56240005 MY56280004 MY56280005 MY56280007 MY56280008
MY56290003 MY56290010 MY56320005 MY56340004 MY56340008 MY56340009
MY56480008 MY56490007 MY57010008 MY57010009 MY57250002 MY57250003
MY57250004 MY57250005 MY57270007 MY57400005 MY57500002 MY57500003

Missing option number on the serial number label

Parts Required:

NONE

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: WN
AUTHOR: CKN

ADDITIONAL INFORMATION:

Situation:

Option number (H50) not able to be serviced by service center. However, option number H50 is not printed on the serial number label for identification of these units.

Solution/Action:

For option H50, unit only able to service by factory. Please send the unit back to factory for further action.

Revision History:

Date	Service Note Revision	Author	Reason for Change
01 Feb 2018	01	CKN	As Published