

U3606A-01

S E R V I C E N O T E

Supersedes:
NONE

U3606A Multimeter - DC Power Supply

Serial Numbers: MY000000000/MY999999999

Self-test error “631” may appear on U3606A when unit is powered ON for the first time

Parts Required:

P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
<input type="checkbox"/> Calibration Required <input checked="" type="checkbox"/> Calibration NOT Required	PRODUCT LINE: WC AUTHOR: KT
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2013
PRINTED IN U.S.A.

April 8, 2013
Rev. 21



Situation:

Customers may see self-test error “631” on the front panel of U3606A during first time powered ON. This happens when the check sum is not restored and it causes a difference in the EEPROM. Error “631” may happen on the affected serial numbers.

Solution/Action:

Customers need to press the “output/SBY” button once when they see this error “631”. With “output/SBY” button turned ON, the check sum will be restored to EEPROM. And, this error “631” will be disappeared.

Revision History:

NONE