## U3606A-02

# S E R V I C E N O T E

Supersedes: NONE

### U3606A Multimeter | Power Supply

Serial Numbers: MY53030002, SG53010006, SG53010007, SG53010008, MY53070023, MY53070021, MY53230001, SG53040001

U3606A unit missing calibration traceability

| <b>Parts</b> | Rea | uired: |
|--------------|-----|--------|
| _ ~ ~        |     |        |

P/N Description Qty.

**NONE** 

#### ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION:   |  |  |  |  |
|--|--|--|--|--|
| MODIFICATION RECOMMENDED   |  |  |  |  |
| ACTION X ON SPECIFIED FAILURE CATEGORY: [[]] AGREEABLE TIME  | STANDARDS  LABOR: 1 Hour   |  |  |  |
| LOCATION [[]] CUSTOMER INSTALLABLE CATEGORY: [[]] ON-SITE (active On-site coverage only) X SERVICE CENTER [[]] CHANNEL PARTNER | SERVICE [[]] RETURN USED [[]] RETURN PARTS: [[]] SCRAP [[]] SEE TEXT |  |  |  |
| AVAILABILITY: PRODUCT'S SUPPORT LIFE   | NO CHARGE AVAILABLE UNTIL: 6 November 2014                           |  |  |  |
| X Calibration Required [[]] Calibration NOT Required   | PRODUCT LINE: WC<br>AUTHOR: SJ                                       |  |  |  |
| ADDITIONAL INFORMATION:  |  |  |  |  |

© AGILENT TECHNOLOGIES, INC. 2013 PRINTED IN U.S.A.



November 6, 2013

Rev. 21

Page 2 of 2 U3606A-02

#### **Situation:**

During recent Agilent internal process audit, it is discovered that the test result file of the unit identified by serial number listed above could not be located in the database. Therefore Agilent would like to proactively withdraw the unit back for verification calibration and for traceability purposes.

#### **Solution/Action:**

Please contact the nearest Agilent Service Centre for calibration request by quoting this service note.

#### **Revision History:**

| Revision<br>Number | Date    | Author | Reason For Change |
|--------------------|---------|--------|-------------------|
| 1.0                | 11/6/13 | SJ     | As published      |
|                    |         |        |                   |