M9202A-01A

S E R V I C E   N O T E

Supersedes:
M9202A-01

M9202A PXI Express (PXIe) 12-bit Wideband IF Digitizer

Affected Software Version: 1.9.x and before

M9202A does not show up in the PXI Express System Description File

Parts Required:
P/N	Description	Qty.
NONE		

Situation:

A bug was found in the PXI peripheral module driver that is responsible for advertising the presence of the M9202A to the PXI resource manager. PXI compliant (non-Agilent) Resource Managers will not discover the M9202A, resulting in the M9202A model information not being written to the corresponding PXI Peripheral Slot Descriptor of the PXI Express System Description file (commonly referred to as the pxiesys.ini file) (see PXI-6 spec http://www.pxisa.org/Specifications.html, section 2.1 and 2.2.7.2).

Solution/Action:

This does not impact the operation of the M9202A nor the system information displayed in the Agilent Connection Expert or the National Instruments Measurement and Automation Explorer.

While waiting for the fix, users may use Agilent Connection Expert to find the peripheral module slot locations and other information for M9202A.

ADMINISTRATIVE INFORMATION

<table>
<tr><td colspan="2">SERVICE NOTE CLASSIFICATION:

<div align="center">INFORMATION ONLY</div></td></tr>
<tr><td>AUTHOR: TP</td><td>PRODUCT LINE: BL</td></tr>
<tr><td colspan="2">ADDITIONAL INFORMATION:

</td></tr>
</table>

© AGILENT TECHNOLOGIES, INC. 2012
PRINTED IN U.S.A.

March 20, 2012

Agilent Technologies