

Supersedes:  
1304A-4

**1304A X-Y DISPLAY**  
**Serial Prefixes 1715A and 1920A**  
**+158V POWER SUPPLY RELIABILITY MODIFICATION KIT**

A small number of units have experienced a +158V power supply failure rate higher than HP's goals. This application oriented problem may be rectified by installing a new A1 mother board which provides a discrete component +158V regulated power supply. Modification Kit HP Part Number 01304-69501 provides the new board, pass transistor, installation instructions, and updated service manual documentation.

Any unit that shipped after 1 October, 1979 that is returned to HP for repair of any failure will have the modification kit installed free of charge.

Units purchased prior to 1 October, 1979 that are returned to HP for a +158V power supply failure will be provided the modification kit; however labor will be billed.

E/OF/WA

8/81-08/BL

Service Note Stock No. 5957-3205

**HEWLETT  
PACKARD**

For more information, call your local HP Sales Office or nearest Regional Office: Eastern (301) 258-2000; Midwestern (312) 255-9800; Southern (404) 955-1500; Western (213) 877-1282; Canadian (416) 678-9430. Ask the operator for Instrument Sales. Or, Write: Hewlett-Packard, 1501 Page Mill Road, Palo Alto, CA 94304. In Europe: Hewlett-Packard S.A., 7, rue du Bois-du-Lan, P.O. Box CH-1217 Meyrin 2, Geneva, Switzerland. In Japan: Yokogawa-Hewlett-Packard Ltd., 29-21, Takaido-Higashi 3-chome, Suginami-ku, Tokyo, 168.