1332A-5

SERVICE NOTE

supersedes: None

HP MODEL 1332A X-Y DISPLAY

All Prefixes

IMPROVED RELIABILITY FOR THE Z-AXIS AMPLIFIER

The preferred replacement for A1C9 and A1C10 is 0160-3665.

The preferred replacement A1C11 is 0160-3670.

ŗ.,

The maximum voltage for A1C9 and A1C10 has been upgraded from 100V to 500V.

The maximum voltage for A1C11 has been upgraded from 100V to 200V.

Insure that the manual is updated to reflect these changes.

VH/rw/WO

Page 1 of 1 04-77/08



For more information, call your local HP Sales Office or East (201) 265-5000 • Midwest (312) 255-9800 • South (404) 955-1500 • West (213) 877-1281. Or, write: Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304. In Europe, Post Office Box 85, CH-1217 Meyrin 2, Geneva, Switzerland. In Japan, Yokogawa-Hewlett-Packard, 1-59-1, Yoyogi, Shibuya-Ku, Tokyo, 151.