

S E R V I C E N O T E

SUPERSEDES: None

15801A Virtual Remote**Release of Revision 1.2 of the Virtual Remote Software****Situation:**

A spelling mistake in the original installation script meant that the original configuration was not correctly saved. The config.sys file was intended to be saved as 'config.old' but as a result of a spelling mistake the script attempted to save the non-existent file 'config.bat'.

The release of a new revision provided the opportunity to modify configuration files associated with the DESQview/X platform. These modifications avoid the possibility of the error message 'Not Enough Memory to Start' appearing when starting Virtual Remote.

The following changes were made to the install1.bat and install3.bat files:

1. The name 'config.bat' was changed to 'config.sys' in install1.bat
2. Comments were added to install1.bat and install3.bat to reflect new version number 1.2
3. Version number 1.2 was embedded in Virtual Remote code
4. Memory allocations in the vrm.dvp and vrmdisp.dvp files were reduced to prevent the error message 'Not Enough Memory to Start' appearing with some computer configurations.

DATE: July 1995

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

SF

1400