S E R V I C E N O T E

SUPERSEDES: None

16339A Component Test Fixture

Serial Numbers: 0000J00000 / 3204J00182

Recommended replacement of miniature banana-plug cable improved persistence

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

Part No. Qty. Description

16339-61621 1 Miniature Banana-plug Cable Assembly

Situation:

The miniature banana-plug cable wire easily snaps when used with the alligator clip.

Solution/Action:

The miniature banana-plug cable has been improved after above serialized unit. The new cable has head-shrinkable tubes on each side roots of its cable (see Figure 1). Replace the entire defective miniature banana-plug cable assembly with the new one if the defective one has no head-shrinkable tube.

Continued

DATE: 26 March 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS:
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE■ ON-SITE■ SERVICE CENTER	SERVICE RETURN USED RETURN INVENTORY: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	RESPONSIBILE UNTIL: 31 March 1995
AUTHOR: YO	ENTITY: 3355	ADDITIONAL INFORMATION:

© 1993 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



16339A-02




Figure 1. Improved Cable Assembly