



### Ⓜ MODEL 1781B DELAY GENERATOR

Serials below 415-01026

### INCREASED MIXED SWEEP STABILITY

If jitter exceeds specification in the above instruments when operating in the MIXED Sweep mode, make the following change.

1. Remove R49, a  $20K \pm 5\%$  1 watt resistor, from large circuit board and reconnect it between violet wire and white-yellow wire on DELAYING SWEEP TIME SWITCH. (A new resistor may be ordered under Ⓜ Stock No. 0689-2035).
2. On the Sweep Generator Schematic of your Model 1781B Operating and Service Manual, relocate R49 to the anode side of CR6 and delete "FROM H."

P

02028-1

7/64-7

