

3070-101

Information Only Service Note

Supersedes:
NONE

E9905E-AS2/N1178-AS2/N1178A-AS3 Async systems or upgrades

Serial Numbers: ALL

Manufacturing ID Number: ALL

The Problem –

In-Circuit Parallel Test(ICPT) software not supported in i3070 software version below 10.0p.

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

Calibration Required

PRODUCT LINE: PL80

Calibration NOT Required

AUTHOR: LKW

ADDITIONAL INFORMATION:

Situation:

For all async systems that is running i3070 software versions below 10.0p, ICPT software will not be supported.


ICPT software is a user interface that operates at the host environment to manage the BT Basic windows operations within each of the module virtual machines (VM) in the async test system.



A parallel test feature license is required in each of the VM for ICPT to establish control to its BT Basic windows. However, this feature license is only support at i3070 software version 10.0p and above. Without this license, ICPT will not be able to detect the modules.

Solution/Action:

Do not use ICPT for all systems running i3070 software version below 10.0p.
Operate the test operations from the BT Basic windows within each of the VM.



Revision History:

Date	Service Note Revision	Author	Reason for Change
12 Nov 2021	01	LKW	As Published