

33502A-02

Information Only Service Note

Supersedes:
NONE

33502A Isolated Amplifier, 2 Channel, 50 Vpp

Serial Numbers: MY49000306 – MY59000415
SG59000107 – SG59000112

The Problem – The LAN MAC address assigned to B2900B series may have a duplicate with the one assigned to 33502A.

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: GM
AUTHOR: WY

ADDITIONAL INFORMATION:

Situation:

If 33502A is connected to the same LAN with B2900B series, there may be conflict and may cause issues related to LAN communication.

Solution/Action:

For solution/action, refer to the service notes for the following models.

Model
B2901BL
B2910BL
B2901B
B2902B
B2911B
B2912B
B2961B
B2962B
B2981B
B2983B
B2985B
B2987B

No action required for 33502A.

Revision History:

Date	Service Note Revision	Author	Reason for Change
17 Nov 2021	01	WanYee	As Published

