

INFORMATION ONLY

33611A-02

S E R V I C E N O T E

Supersedes:
NONE

33611A Waveform Generator

Serial Numbers: ALL

Firmware on this instrument should be updated to the latest revision before any repairs are initiated on this product.

Parts Required:

P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
<input type="checkbox"/> Calibration Required	PRODUCT LINE: GM
<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR: MDB
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2014
PRINTED IN U.S.A.

April 7, 2014
Rev. 22



Situation:

False error messages at power-on were generated with previous versions of the firmware.

Solution/Action:

The firmware in the 33611A should be updated to the latest version before proceeding with repairs. This will avoid false error messages at power-on. Go to www.agilent.com/find/33611A to find the latest revision of the firmware.

Revision History:

Revision Number	Date	Author	Reason For Change
1.0	4-04-2014	MDB	As published