34461A-08A

# Modification Recommended Service Note

Supersedes: 34461A-08

# 34461A - 61/2 Truevolt Digital Multimeter

Serial Numbers: MY60001911 - MY60003066

The Problem - Incorrect label printing on the DMM front panel .

# Parts Required:

P/N Description Qty.

5183-1670 Label 1000VDC 750VAC 1pc

#### ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 0.5	Hours	
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) [X] SERVICE CENTER [[]] CHANNEL PARTNERS	SERVICE: [[]] RET INVENTORY: [[]] SCF [X] SEE	RAP PART	-
AVAILABILITY	: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABI	_E UNTIL: 09 Feb	2023
	[[]] Calibration Required [X] Calibration NOT Required	PRODUCT LINE: GM AUTHOR: WY		

ADDITIONAL INFORMATION:



#### Situation:

The input voltage rating on the front panel was incorrectly printed as 750VDC instead of 750 VAC. The correct input voltage rating should be 1000VDC, 750 VAC.

The incorrect printing does not impact the product functionality nor safety requirement.



#### Solution/Action:

# Customers

Upon request, the label can be updated accordingly when unit is returned to service center for annual calibration.

# Keysight service centers

Perform the following steps when you receive request to update the label:

- 1. Order a 5183-1670 label.
- 2. Use a tweezer to grab the label and place it on the front panel to cover the voltage rating as shown below.





3. After applying the label, it should look like the picture below:



# Revision History:

Date	Service Note Revisio	Author	Reason for Change
25 Jan 2021	01	WanYee	As Published
09 Feb 2021	02	WanYee	Revised to include the label placement.