

3458A-19B

# Information Only Service Note

Supersedes:  
3458A-19A

## 3458A 8½ Digital Multimeter

Serial Numbers: ALL

**The Problem** – The A5 assembly update kit 03458-80047 & 03458-80048 are now available until gone. The replacement kit (03458-80049) consists of two parts and an installation note.

### Parts Required:

| P/N         | Description              | Qty. |
|-------------|--------------------------|------|
| 03458-80049 | Memory Kit, 148kB (RoHS) | 1    |

### ADMINISTRATIVE INFORMATION

---

Calibration Required  
 Calibration NOT Required

PRODUCT LINE: GM  
AUTHOR: WY

---

ADDITIONAL INFORMATION:

---

**Situation:**

03458-80049 is the replacement kit for 03458-80047 and 03458-80048.

The replacement kit contains the new A5 PCA (RoHS) 03458-66675, a cable (03458-61611) and an installation note.

By replacing the A5 memory kit (03458-80049), it will upgrade the memory of any standard 3458A to 148kB.

**Solution/Action:**

Please order the replacement kit when 03458-80047 or 03458-80048 is no longer available.

**Revision History:**

| Date        | Service Note Revision | Author | Reason for Change      |
|-------------|-----------------------|--------|------------------------|
| 17 Apr 2006 | 01                    | DAH    | As Published           |
| 10 Apr 2007 | 02                    | LH     | Update serial numbers  |
| 24 Mar 2020 | 03                    | WanYee | Update Replacement P/N |
|             |                       |        |                        |
|             |                       |        |                        |