

34921A-03

# Information Only Service Note

Supersedes:  
NONE

## 34921A 40-Channel Armature Multiplexer for 34980A

Serial Numbers: ALL

**The Problem** – New Keysight Color

### Parts Required:

P/N	Description	Qty.
34921-60001	40-Channel Armature Multiplexer new replacement unit	1
34921-66001	Armature Multiplexer,40-Channel new replacement unit (Rebranded)	1

### ADMINISTRATIVE INFORMATION

Calibration Required  
 Calibration NOT Required

PRODUCT LINE: PLGM  
AUTHOR: SL

ADDITIONAL INFORMATION:

**Situation:**

The outlook of the instrument is experiencing a color change to comply with the new Keysight product color scheme. The redesigned 34921A provides the same product performance, specifications, and is 100% compatible with the existing 34921A.

**Solution/Action:**

**Keysight customers:**

No action is needed.

**Keysight service centers:**

For new unit replacement below MY56487385, use the part number 34921-60001 (Armature Multiplexer, 40-Channel). These parts are available as UTG. Once the parts are depleted, use the rebranded part numbers 34921-66001 (Armature Multiplexer, 40-Channel rebranded).

For new unit replacement of MY56487385 and above, use directly the rebranded part numbers 34921-66001 (Armature Multiplexer, 40-Channel rebranded).

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
13 Feb 2020	01	SL	As Published