

34922A-03

Information Only Service Note

Supersedes:
NONE

34922A 70-Channel Armature Multiplexer for 34980A

Serial Numbers: ALL

The Problem – New Keysight Color

Parts Required:

P/N	Description	Qty.
34922-60001	70-Channel Armature Multiplexer new replacement unit	1
34922-66001	Armature Multiplexer,70-Channel new replacement unit (Rebranded)	1

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: PLGM
AUTHOR: SL

ADDITIONAL INFORMATION:

Situation:

The outlook of the instrument is experiencing a color change to comply with the new Keysight product color scheme. The redesigned 34922A provides the same product performance, specifications, and is 100% compatible with the existing 34922A.

Solution/Action:

Keysight customers:

No action is needed.

Keysight service centers:

For new unit replacement below MY56483517, use the part number 34922-60001 (Armature Multiplexer, 70-Channel). These parts are available as UTG. Once the parts are depleted, use the rebranded part numbers 34922-66001 (Armature Multiplexer, 70-Channel rebranded).

For new unit replacement of MY56483517 and above, use directly the rebranded part numbers 34922-66001 (Armature Multiplexer, 70-Channel rebranded).

Revision History:

Date	Service Note Revision	Author	Reason for Change
13 Feb 2020	01	SL	As Published