

Information Only Service Note

Supersedes: NONE

34939A 64-Channel Form A General Purpose Switch for 34980A

Serial Numbers: MY62120001/ MY99999999 SG62120001/SG99999999

The Problem - New Orbital Sanded Covers for 34980A modules

Parts Required: N/A

ADMINISTRATIVE INFORMATION

[]] Calibration Required [X] Calibration NOT Required PRODUCT LINE: PLGM AUTHOR: MS

ADDITIONAL INFORMATION:



© Keysight Technologies 2015-2022 Information Only Service Note Version 1.2 | June 28, 2022| Page **1** of **3**

Situation:

34939A modules beginning with serial numbers MY62120001/SG62120001 or greater, will have new furnishings that have orbital sanded covers to avoid roller marks on the material. Refer to image 1 below:



Image 1: New Furnishing with Orbital Sanding

34939A modules with serial numbers less than MY62120001/SG62120001 will have glossy surfaces as shown in image 2.



Image 2: Old Furnishing with Glossy Surface

These changes have no impact on the module's performance.

Solution/Action: No Action is needed.

Service Service Date Note Author Reason for Change 28 June 2022 03 MS As Published