

34941A-01

Information Only Service Note

Supersedes:
NONE

34941A Quad 1x4 50Ohm 3GHz Multiplexer Module for 34980A

Serial Numbers: ALL

The Problem – New Keysight Color

Parts Required:

P/N	Description	Qty.
34941-60002	Quad 1x4 50 Ohm 2.5GHz Multiplexer New Replacement Unit	1
34941-66002	Quad 1x4 50 Ohm 2.5GHz Multiplexer New Replacement Unit (Rebranded)	1

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: PLGM
AUTHOR: SL

ADDITIONAL INFORMATION:

Situation:

The outlook of the instrument is experiencing a color change to comply with the new Keysight product color scheme. The redesigned 34941A provides the same product performance, specifications, and is 100% compatible with the existing 34941A.

Solution/Action:

Keysight customers:

No action is needed.

Keysight service centers:

For new unit replacement below MY56481116/ SG56480006, use the part number 34941-60002 (Quad 1x4 500hm 3GHz Multiplexer). These parts are available as UTG. Once the parts are depleted, use the rebranded part numbers 34941-66002 (Quad 1x4 500hm 3GHz Multiplexer rebranded).

For new unit replacement of MY56481116/SG56480006 and above, use directly the rebranded part numbers 34941-66002 (Quad 1x4 500hm 3GHz Multiplexer rebranded).

Revision History:

Date	Service Note Revision	Author	Reason for Change
13 Feb 2020	01	SL	As Published