

34942A-01

Information Only Service Note

Supersedes:
NONE

34942A Quad 1x4 75Ohm 1.5GHz Multiplexer Module for 34980A

Serial Numbers: ALL

The Problem – New Keysight Color

Parts Required:

P/N	Description	Qty.
34942-60001	Quad 1x4 75 Ohm 1.5GHz Multiplexer new replacement unit	1
34942-66001	Quad 1x4 75 Ohm 1.5GHz Multiplexer new replacement unit (Rebranded)	1

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: PLGM
AUTHOR: SL

ADDITIONAL INFORMATION:

Situation:

The outlook of the instrument is experiencing a color change to comply with the new Keysight product color scheme. The redesigned 34942A provides the same product performance, specifications, and is 100% compatible with the existing 34942A.

Solution/Action:

Keysight customers:

No action is needed.

Keysight service centers:

For new unit replacement below MY56480103, use the part number 34942-60001 (Quad 1x4 750hm 1.5GHz Multiplexer). These parts are available as UTG. Once the parts are depleted, use the rebranded part numbers 34942-66001 (Quad 1x4 750hm 1.5GHz Multiplexer rebranded).

For new unit replacement of MY56480103 and above, use directly the rebranded part numbers 34942-66001 (Quad 1x4 750hm 1.5GHz Multiplexer rebranded).

Revision History:

Date	Service Note Revision	Author	Reason for Change
13 Feb 2020	01	SL	As Published