

34942A-02

# Information Only Service Note

Supersedes:  
NONE

## 34942A Quad 1x4 75 Ohm 1.5 GHz Multiplexer Module for 34980A

Serial Numbers: MY62120001/ MY999999999  
SG62120001/SG999999999

**The Problem** – New Orbital Sanded Covers for 34980A modules

**Parts Required:**  
N/A

### ADMINISTRATIVE INFORMATION

---

Calibration Required  
 Calibration NOT Required

PRODUCT LINE: PLGM  
AUTHOR: MS

---

ADDITIONAL INFORMATION:

---

**Situation:**

34942A modules beginning with serial numbers MY62120001/SG62120001 or greater, will have new furnishings that have orbital sanded covers to avoid roller marks on the material. Refer to image 1 below:




Image 1: New Furnishing with Orbital Sanding

34942A modules with serial numbers less than MY62120001/SG62120001 will have glossy surfaces as shown in image 2.



Image 2: Old Furnishing with Glossy Surface

These changes have no impact on the module's performance.

**Solution/Action:**  
No Action is needed.

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
28 June 2022	02	MS	As Published