

34945A-04

Information Only Service Note

Supersedes:
NONE

34945A Switch/Attenuator Driver for 34980A

Serial Numbers: MY62120001/ MY999999999
SG62120001/SG999999999

The Problem – New Orbital Sanded Covers for 34980A modules

Parts Required:
N/A

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: PLGM
AUTHOR: MS

ADDITIONAL INFORMATION:

Situation:

34945A modules beginning with serial numbers MY62120001/SG62120001 or greater, will have new furnishings that have orbital sanded covers to avoid roller marks on the material. Refer to image 1 below:




Image 1: New Furnishing with Orbital Sanding

34945A modules with serial numbers less than MY62120001/SG62120001 will have glossy surfaces as shown in image 2.



Image 2: Old Furnishing with Glossy Surface

These changes have no impact on the module's performance.

Solution/Action:
No Action is needed.

Revision History:

Date	Service Note Revision	Author	Reason for Change
28 June 2022	04	MS	As Published