2/0504 01

# Information Only Service Note

Supersedes: NONE

# 34950A 64-bit Digital I/O with Memory and Counter for 34980A

Serial Numbers: ALL

The Problem - New Keysight Color

# Parts Required:

P/N Description Qty. 34950-60001 64-bit DIO Module with Memory and Counter new replacement unit 1 DIO Module with Memory and Counter,64-bit new replacement unit (Rebranded)

## ADMINISTRATIVE INFORMATION

[[]] Calibration Required PRODUCT LINE: PLGM
[X] Calibration NOT Required AUTHOR: SL

ADDITIONAL INFORMATION:



#### Situation:

The outlook of the instrument is experiencing a color change to comply with the new Keysight product color scheme. The redesigned 34950A provides the same product performance, specifications, and is 100% compatible with the existing 34950A.

### Solution/Action:

# Keysight customers:

No action is needed.

#### Keysight service centers:

For new unit replacement below MY56480558, use the part numbers 34950-60001 (Digital I/O Module with Memory and Counter). These parts are available as UTG. Once the parts are depleted, use the rebranded part numbers 34950-66001 (Digital I/O Module with Memory and Counter rebranded).

For new unit replacement of MY56480558 and above, use directly the rebranded part numbers 34950-66001 (Digital I/O Module with Memory and Counter rebranded).

# Revision History:

Date	Service Note Revision	Author	Reason for Change	
13 Feb 2020	01	SL	As Published	
13 Feb 2020	UT	3L	AS Published	