							3	495	1A-	01
S	Ε	R	V	C	Ε	N		0	Τ	Ε

Supersedes: NONE

34951A 4-channel isolated D/A converter with waveform memory

Serial Numbers: MY44001489 to MY44001609 and SG44000154 to SG44000158

**Certificates of Calibration Have Missing Information for the Calibration Equipments Used** 

<b>Parts</b>	Req	uired:	
--------------	-----	--------	--

P/N Description Qty.

**NONE** 

## **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:					
INFORMATION ONLY					
AUTHOR: TP	PRODUCT LINE: SP				
ADDITIONAL INFORMATION:					

© AGILENT TECHNOLOGIES, INC. 2009 PRINTED IN U.S.A.



September 1, 2009

Rev. 16

Page 2 of 2 34951A-01

## **Situation:**

It has been recently determined that some 34951A Certificates of Calibration (CoC) do not state the trace number and calibration due date for the calibration equipments used. In transferring the calibration procedure to a new computer, the calibration program did not take the information from the log file as it should which results in missing the information when printing the CoC.

## **Solution/Action:**

Agilent has taken the action to correct the certificates of calibration and upload the corrected versions to a website, where customers can download the correct certificates. Please note that this issue only affects the certificates of calibration of the cards. The cards themselves are calibrated correctly.

If your serial number falls into the affected serial number ranges, please download the "Infoline\_CoC.PPT" file at <a href="ftp://ftp.agilent.com/pub/mpusup/">ftp://ftp.agilent.com/pub/mpusup/</a> for instructions on how to get the correct certificate of calibration.