

34952A-02

Information Only Service Note

Supersedes:
NONE

34952A Multifunction Module with 32-bit DIO, 2-ch D/A and Totalizer for 34980A

Serial Numbers: ALL

The Problem – New Keysight Color

Parts Required:

P/N	Description	Qty.
34952-60001	Multifunction Module with 32-bit DIO, 2-ch D/A and Totalizer new replacement unit	1
34952-66001	Multifunction Module with 32-bit DIO, 2-ch D/A and Totalizer new replacement unit (Rebranded)	1

ADMINISTRATIVE INFORMATION

Calibration Required
 Calibration NOT Required

PRODUCT LINE: PLGM
AUTHOR: SL

ADDITIONAL INFORMATION:

Situation:

The outlook of the instrument is experiencing a color change to comply with the new Keysight product color scheme. The redesigned 34952A provides the same product performance, specifications, and is 100% compatible with the existing 34952A.

Solution/Action:

Keysight customers:

No action is needed.

Keysight service centers:

For new unit replacement below MY56480605, use the part numbers 34952-60001 (Multifunction Module with 32-bit Digital I/O, 2-Channel D/A and Totalizer). These parts are available as UTG. Once the parts are depleted, use the rebranded part numbers 34952-66001 (Multifunction Module with 32-bit Digital I/O, 2-Channel D/A and Totalizer rebranded).

For new unit replacement of MY56480605 and above, use directly the rebranded part numbers 34952-66001 (Multifunction Module with 32-bit Digital I/O, 2-Channel D/A and Totalizer rebranded).

Revision History:

Date	Service Note Revision	Author	Reason for Change
13 Feb 2020	01	SL	As Published