

34970A-16

S E R V I C E N O T E

Supersedes: None

34970A - Data Acquisition / Data Logger Switch Unit

Serial Numbers: US37019742 and below

Cooling fan must match the cover type. If a new cover with ventilation holes is used, cooling fan assembly must be part number 34970-68511

Parts Required:

P/N 34970-68511 Description Fan Assembly Qty. 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
<input type="checkbox"/> Calibration Required <input checked="" type="checkbox"/> Calibration NOT Required	PRODUCT LINE: SP AUTHOR: TC
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2013
PRINTED IN U.S.A.

March 29, 2013

Rev. 21



Situation:

The 34970A with the 34901A multiplexer thermocouple measurement performance is characterized with the cooling fan type that is dependent on the instrument cover type. Older units have covers with no ventilation holes. Newer covers have ventilation holes and must use the 34970-68511 fan assembly.

Solution/Action:

If the old cover without ventilation holes is replaced with a new cover with ventilation holes, change the fan assembly to 34970-68511.

Revision History:

Revision Number	Date	Author	Reason For Change
1.0	04-01-2013	TC	As published