

S E R V I C E N O T E

SUPERSEDES: None

HP 35652A/B Input/Signal Conditioning Module**Serial Numbers:** 0000A00000 / 9999Z99999**Model Number Programming****Parts Required:**

35650A
 35651A/B/C
 35652A/B
 35653A/B/C

Situation:

When replacing the 35652A/B A1 Digital Board, you must not only write the serial number into NVRAM, but also the Model number. This is because the A1 assembly is the same for the A and B 35652 modules.

Solution/Action:

The 35652A/B model number can be changed using the diagnostics terminal (RS-232 port on the 35651A/B/C) on the signal processor module.

To set the model number to HP35652B, use the Diagnostics Terminal "Send Command" function and send:

TST 114,"AtroposHP35652B "

NOTE: There are 4 spaces after the HP35652B in the above string.

Change the "B" to an "A" with this same procedure.

DATE: January 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

MJL

A100