

37701A-08

S E R V I C E N O T E

SUPERSEDES: None

HP 37701A T1 Tester

Serial Numbers: 0000U00000/9999U99999

In the event 37701-60001, 37701-60211, 37701-60511 fails, use 37702-60001 for replacement

Situation

All the above assemblies are replaced by 37702-60001.

If instrument has firmware revision more than or equal to 3127 then the correct LCA's are fitted and board is a direct replacement.

If instrument has firmware revision less than 3127, then U5 and U21 should be used from the old assembly.

Description	Identifier	Part No.
F/W Rev less than 3127	U5 & U21	1820-6539 (3030)
F/W Rev more than or equal to 3127	U5 & U21	1820-6533 (3042)

DATE: July 1995

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
GS	1400	

© 1995 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

