

S E R V I C E N O T E

SUPERSEDES: NONE

3784A Transmission Analyzer**Serial Numbers:** 0000U00000 / 9999U99999**Replacing the Power Supply Assembly (A30)****To Be Performed By:** Agilent-Qualified Personnel or Customer**Situation:**

One of two possible Power Supply assemblies may be fitted to the 3784A. Part Number 03785-60030 is the Power Supply assembly used in standard and option 006 instruments. Part Number 03785-60130 is the Power Supply assembly used in options 002 and 008 and caters for the increased power requirements of these options.

Ensure when replacing either of these assemblies the correct replacement is fitted.

DATE: 1 June 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

JMW

ENTITY:

1400

ADDITIONAL INFORMATION:

