

S E R V I C E N O T E

SUPERSEDES: None

HP 4155A Semiconductor Parameter Analyzer

Serial Numbers: 0000A00000 / 9999Z99999

Flexible Disk Drive Discontinuance and Replacement

Duplicate Service Notes: 4156A-09

To Be Performed By: HP-Qualified Personnel

Parts Required:

See test.

Situation:

The flexible disk drive (HP P/N 0950-2348) for the HP 4155A was discontinued.

DATE: July 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

MO

ENTITY:

3300

ADDITIONAL INFORMATION:

Solution / Action:

The replacement of 0950-2348 is 0950-3108. The HP 4155As with the following serial numbers are shipped with the new FDD (0950-3108):

HP 4155A: JP10A00955 and above

The FDD cable and the FDD cover were also changed to fit the new FDD:

	Existing	Replacement
FDD	0950-2348	0950-3108
FDD Cable	04155-61615	04155-61620
FDD Cover	04155-04003	04155-04030

If an old FDD (0950-2348) needs to be replaced and 0950-2348 is no longer supplied, order the new FDD, new FDD cable, and new FDD cover.