4156A-02

S	Е	R	V	Ι	С	Е	٦	١	0	Т	Ε
							SUPERS	EDE	S: None		
415	6A Pree	cision S	Semic	ondu	ctor Pa	ramet	er Analyz	zer			
Seria	al Numbe				A00240 10A0024	7					
Pow	ver supp	ply mod	lule re	eplace	ement t	o preve	ent shut-d	owr	n failure	es.	
4155 4150	licate Ser A-02 1A-01			0.116		·					
	e Perforn	-	gilent-	Qualifi	ed Persor	nnel					
Part	s Require No. 5-69003	ed: Qty. 1		escripti ower Su		dule (for	the 4155A/4	4156	A)		
									C	ontinued	
							DATE: Au	gust	1994		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:							
	MODIFICATION	RECOMMENDED					
ACTION CATEGORY:	 IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME 	STANDARDS: Labor 0.5 Hour					
LOCATION CATEGORY:	CUSTOMER INSTALLABLE	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT					
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: September 1997					
AUTHOR: IT	ENTITY: 3301	ADDITIONAL INFORMATION:					

© 1994 AGILENT TECHNOLOGIES
PRINTED IN U.S.A.



Situation:

The 4155A/4156A/41501A units within the listed serial number range, and having a power supply module with an EDC (Engineering Data Code) less than 3424, may have a power supply shut-down problem. This problem shows the following phenomena.

- Units hang up during the power on selftest.
- CAUTION 308: Unknown emergency (SMUC time out) is displayed intermittently during the operation.
- During the operation, power of the units is cycling and all LEDS on the front panel will be flashing.

Solution/Action:

Replace a faulty power supply module of the units using an exchange program. Power supply modules with an EDC equal to 3424 or greater have been modified at the factory, and SMO/SME already stocks the modified supply modules as an exchange part.

An EDC is in the form YYWW and is usually found on a white label on the side panel of power supply modules.

Where: YY=YEAR-1960 (Example: If YY=33, the year is 1993)

WW=WEEK (Example: If WW=20, it indicates the 20th week of YY)

Following shows an example of a label that lists an EDC.

04155-60003 33-3424 << 3424 is the EDC 00484-3427 MADE IN JAPAN

If the 4155A/4156A has the 41501A expander, it is required to replace both power supply of the 4155A/4156A and 41501A.