

4156A-04

S E R V I C E N O T E

SUPERSEDES: None

HP 4156A Precision Semiconductor Parameter Analyzer

Serial Numbers: JP10A00101 / JP10A00114

Rotary knob rubs the front panel

To be Performed by: HP-qualified personnel

Parts Required:

HP P/N	Qty	Description
04155-66506	1	Front Keyboard

Situation:

When you rotate the knob on the front panel, the knob may rub the front panel.

Solution/Action:

Replace the Front Keyboard.

DATE: October 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 1.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> HP LOCATION	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
		USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	HP RESPONSIBLE UNTIL: October 1997	
AUTHOR: MN	ENTITY: 3301	ADDITIONAL INFORMATION:	

