

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**4268A-04**

# S E R V I C E                      N O T E

Supersedes:  
[None]

## Agilent 4268A 120Hz/1kHz Capacitance Meter

**Serial Numbers: See Solution / Action**

### **Power Supply Switch Part Number Change**

**Parts Required: See Solution / Action**

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: <b>INFORMATION ONLY</b>
AUTHOR: TO    PRODUCT LINE: WN
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2003  
PRINTED IN U.S.A.



February 10, 2003

**Situation:**

The wire assembly (P/N 04268-61631) with power switch of the 4268A was obsoleted and replaced with new parts.

**Solution/Action:**

When replacing the wire assembly, order appropriate parts depending on the serial number of the 4268A.

**Serial Number: JP1KF00847 and below**

When replacing the wire assembly (P/N 04268-61631), replace with the new parts shown in Table 2. Fix the wire assembly (P/N 04268-61634) and angle (P/N 04268-01203) with two screws (0515-0914).

**Serial Number: JP1KF00848 and above**

When replacing the wire assembly or angle, use the replacement parts listed in Table 2

**Table 1 Old Part**

Part Number	Qty.	Description
04268-61631	1	Wire assembly with power switch

**Table 2 New Replacement Parts**

Part Number	Qty.	Description
04268-61634	1	Wire assembly with power switch
04268-01203	1	Angle
0515-0914	2	Screw to fix the wire assembly and angle