

4287A-06B

S E R V I C E N O T E

Supersedes:
4287A-06A

4287A RF LCR Meter

Serial Numbers: JP1KGxxxxx, JP2KGxxxxx, MY432xxxxx

Part Number Change for the LAN I/F Card, the CPU part, ISA GPIB Card and LCD (Windows98 compliance)

Parts Required: See Solution/Action

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: jm PRODUCT LINE: WN

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007
PRINTED IN U.S.A.



February 21, 2007

Situation:

Part numbers for the LAN I/F card, the CPU part, ISA GPIB Card and LCD have been changed.

Solution/Action:

For serial number JP1KGxxxxx, JP2KGxxxxx, MY432xxxxx order the new part number instead.

Old P/N	New P/N	Description
1150-7816	5188-1352	OEM Network Interface Card
1821-3660	5188-1353	IC Pentium P55C
82341C #002	5188-1360	ISA GPIB CARD
1818-8149 or 1818-8973	5188-4435	DIMM 64MB
2090-0396	2090-0897	LIQUID CRYSTAL DISPLAY 8.4IN TFT
04287-25004	04287-25014	GASKET
E4991-00606	E4991-00609	CASE SHIELDS

- End of Document -